

4800 Ashford Dunwoody Road Dunwoody, Georgia 30338 dunwoodyga.gov | 678.382.6700

MEMORANDUM

To: Mayor and City Council

From: Carl Thomas

Date: April 8, 2019

Subject: Memorandum - FUNDING AUTHORIZATION FOR 1352

WYNTERCREEK ROAD STORMWATER REPAIRS

ITEM DESCRIPTION

Approval of Funding for Stormwater Pipe Repairs at **1352 Wyntercreek Road**. Estimate cost, plus 10% contingency, is **\$71,538.50**.

BACKGROUND

Structural impairments were identified after a citizen called about a sinkhole on February 7, 2019. A previous inspection by the city on 12/22/2016 indicated the pipes were in fair condition, but no sinkholes were observed at that time.

Proposed repairs have been identified using CCTV inspections and require:

- Lining approx. 60 linear feet of corrugated metal pipe
- Dig and Replace approx. 55 linear feet of 36 inch corrugated metal pipe
- Pipe invert repair with flowable fill
- Sinkhole repair
- Reset elevation of junction box & install concrete invert

If approved, this project would be funded from the 2019 Stormwater Repairs & Maintenance Budget.

RECOMMENDED ACTION

Staff recommends approving \$71,538.50 in funding for Stormwater Pipe Repairs at 1352 Wyntercreek Road.



4800 Ashford Dunwoody Road Dunwoody, Georgia 30338 dunwoodyga.gov | 678.382.6700


SINKHOLE FORMING AROUND DAMAGED JUNCTION BOX





4800 Ashford Dunwoody Road Dunwoody, Georgia 30338 dunwoodyga.gov | 678.382.6700

STRUCTURAL FAILURE IN PIPE



IPR Southeast LLC						
ESTIMATE - RFP 18-04 2019 STANDBY STORMWATER REPAIR UNIT CONTRACT						
PROJECT LOCATION:	1352 Wyntercreek Road Dunwoody, GA 30338					
DATE ESTIMATE PREPARED:	20-Feb-19					
ESTIMATE PREPARED BY:	Dan Guse					
ESTIMATE AMOUNT:	\$65,035.00					
10 % CONTINGENCY:	\$6,503.50					
ESTIMATE GRAND TOTAL:	\$71,538.50					

Pre-Li	ning Work:
	Pre CCTV and Cleaning
	Specialty Cleaning - Man Entry to remove rocks throughout pipes
	Locate, Raise, Uncover Buried Junction Box - 01815
	Dig and Replace 55 LF of 36" pipe between 01815 and 00186
	Excavate downstream channel
	Clear brush around Catch Basin - 00185
	Remove steps alongside house, Replace after open cut completed
	Invert Repair between 00185 and 01815
Lining	y Work:
	CIPP Lining - approx. 90 LF x 36" x 16.5mm
Post I	ining Work:
	Post CCTV
	Restoration after open cut - Fescue sod
	Seal ends of Lined Pipes
	Invert Installation in three structures

ITEM #	Description	Unit	Unit Price	Quantity	Total Costs	
	General Conditions					
1	Mobilization	EA	\$ 2,000.00	1.00	\$ 2,000.00	
2	Out of Scope Work, Foreman	HR	\$ 85.00	40.00	\$ 3,400.00	
3	Out of Scope Work, Laborer	HR	\$ 70.00	80.00	\$ 5,600.00	
	Traffic Control					
5	Traffic Control Minor 2 - Includes Cones and Signage	DA	\$ 1,850.00	2.00	\$ 3,700.00	
	TV Inspection and Jet-Vac Cleaning					

7	CCTV Storm (w/ DVD & Report)	LF	۲	2.50	1.45.00	¢	262.50
,		LI	\$	2.50	145.00	\$	362.50
33	Storm Cleaning (25% or greater)	LF	4	40.25	00.00	Φ.	022.50
33	36" Pipe - Cleaning 25% or greater	LF	\$	10.25	90.00	\$	922.50
	Special Storm Line Cleaning						
	Roots, Rocks, Debris				00.00		1 (2000
44	12" to 36" Pipe	LF	\$	18.00	90.00		1,620.00
45	42" to 96" Pipe	LF	\$	35.00		\$	-
	Spiral Rib CMP						
	includes excavation, backfill, & compaction						
50	36" SRCMP	LF	\$	50.00	55.00	\$	2,750.00
	Additional Depth for Pipes						
	includes excavation, backfill, & compaction						
77	Invert > 8.1' to 12'	LF	\$	50.00	25.00	\$	1,250.00
	Flowable Paved Pipe Invert						
125	36" Diameter	LF	\$	45.00	10.00	\$	450.00
	Round Precast Manholes						
191	4' Round Precast MH w/ Ring & Cover	VF	\$	455.00	5.00	\$	2,275.00
	Misc & Special Structures/Components						
209	Invert Installation, 4' Dia	EA	\$	275.00	3.00	\$	825.00
213	Uncover Buried JB (<4')	EA	\$	400.00	1.00	\$	400.00
	Grout Connection to Structure						
227	36" Grout Each End to Structure	EA	\$	250.00	4.00	\$	1,000.00
	Lining Requirements						
	CIPP (12' or less in depth)						
	Includes Pre and Post TV during lining						
242	36" - 16.0mm (.6299")	LF	\$	145.00	90.00	\$	13,050.00
259	Add Thickness Per 1.5mm -36"	LF	\$	5.00	90.00	\$	450.00
	Inversion Setup						
270	Inversion Setup Charge 15-36" CIPP	EA	\$	900.00	1.00	\$	900.00
	Earthwork & Grading						
362	Tree Removal 6"- 12"	EA	\$	550.00	1.00	\$	550.00
365	Clear & Grubbing	SY	\$	12.50	10.00	\$	125.00
366	Channel Excavation	CY	\$	10.00	10.00		100.00
368	Haul-In Structural Fill Material	CY	\$	50.00	75.00		3,750.00
369	Haul-Off Soil Material	CY	\$	50.00	75.00		3,750.00
	Erosion Control				. 3 . 3 0		j. 2 0 0
373	Stone Rip Rap Type I in Place	SY	\$	60.00	20.00	\$	1,200.00
379	Install & Remove Type C Silt Fence-ALT	LF	\$	6.00	120.00		720.00
388	Sodding Complete - Fescue	SY	\$	5.75	260.00		1,495.00
392	Topsoil Complete	CY	\$	30.00	50.00		1,500.00
393	Pine Straw	SY	\$	2.50	30.00		75.00
232	FINE Suaw	31	>	2.50	30.00	\$	/5.00

	Miscellaneous Items				
406	Connect to Existing Structures	EA	\$ 750.00	2.00	\$ 1,500.00
407	Debris Removal, Tandem Dump Truck	Load	\$ 800.00	1.00	\$ 800.00
409	Removal of Existing Drainage Structure	EA	\$ 850.00	1.00	\$ 850.00
410	Removal Existing Pipe all Types and Sizes	LF	\$ 65.00	55.00	\$ 3,575.00
412	Stone #57	Ton	\$ 42.00	20.00	\$ 840.00
418	Bypass pump setup-equipment and hose placement	EA	\$ 850.00	2.00	\$ 1,700.00
419	4" Pumping Operation Time	HR	\$ 55.00	20.00	\$ 1,100.00
432	Reset Existing Headwall	EA	\$ 450.00	1.00	\$ 450.00
	TOTAL ESTIMATE				\$65,035.00