




Department



Report Criteria

- Type is **Corrective, Projects** or **Request**
- Status is not equal to **Denied**
- Department is **MS - Peachtree Charter Middle Facility**
- Requested is greater than **06/01/2019**

Work Order #	Reason	Asset ID	Parent Location	ZoneName	Shop Name	Requested
(Site Not Specified)						
(Site Not Specified) > Region 1						
95821	Roof Leak I have Three Rooms Leaking When it Rain or When we Stripping The floors it Leak down the Wall or the Ceiling tile	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	ROOF	6/13/2019 6:15:00 AM
96201	Miscellaneous In The 8th Grade pod Boys Restroom The Wall Need Sheet Rock Rep196	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	CARPENTRY	6/19/2019 9:42:00 AM
96691	Miscellaneous I have two Room 615 618 on the 6th Grade Need Sheet Rock Repair and i also need Seven Door Stops	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	CARPENTRY	6/26/2019 10:21:00 AM
96788	Miscellaneous MR Hindwin Ward We need New Carpet in the Band Room. it is at the point the carpet extractor or Shampooing Will not Clean the Carpet	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	CARPENTRY	6/27/2019 1:21:00 PM
98370	wash exterior of trailer, paint section where peeling has occurred. replace section as needed.	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	CARPENTRY	7/9/2019 4:02:00 PM
98554	Classroom - T1 - Remove damage exterior siding and replace with 4 X 8 Hardie Plank rough saw finish. Cover joints with trim and caulk all edges. Replace all broken tiles across joints in quad PODS - use leveling compound or hydraulic cement to prevent future cracking. See Chris Jackman for more details	PEACHTREE CHARTER MS - 1- CLASSROOM TRAILER-T1	Classroom Trailer	Region 1	CARPENTRY	7/14/2019 12:22:00 PM
98556	Classroom - T1 Sand and paint stall partitions and doors in all restrooms in the 3 Quad PODS.	PEACHTREE CHARTER MS - 1- CLASSROOM TRAILER-T1	Classroom Trailer	Region 1	PAINTING / PRESSURE WASHING	7/14/2019 12:37:00 PM
98783	The boy's bathroom 3rd urinal stall needs to be fixed.Location is across from room 714. The girl's bathroom 3rd stall door needs to be fixed.Location across from room 740. " urgent" Thank You!	PEACHTREE CHARTER MS-MAIN LEVEL	Peachtree Charter MS - 1 (Winward)	Region 1	CARPENTRY	7/16/2019 6:44:00 AM
98882	Kitchen Dish Machine has no power. No power/bad booster heater. Electrician for repairs. Thanks	PEACHTREE CHARTER MS-MAIN LEVEL	Peachtree Charter MS - 1 (Winward)	Region 1	ELECTRICAL	7/17/2019 6:10:51 AM
99021	There's broken sheet rock on the base boards in cafeteria. (Needs repair)Thank You.	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	CARPENTRY	7/18/2019 7:14:00 AM

Work Order #	Reason	Asset ID	Parent Location	ZoneName	Shop Name	Requested
99064	when, entering on campus,the round about circle.The base of the light pole is leaning over. Also, a Do Not Enter sign leaning as well.	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	ELECTRICAL	7/18/2019 11:08:00 AM
99402	In the gym we have two leaks which, occur when it rains. In coach's James office room 513 there water leaking from the ceiling.	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	ROOF	7/23/2019 2:05:00 PM
99407	In Pod T09- T12 The exit sign is hanging. need to be fix.	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	ELECTRICAL	7/23/2019 2:32:00 PM
99519	we have two new employees that need keys. "urgent"	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	LOCKSMITH	7/24/2019 5:12:00 PM
99653	I'm reaching out on behalf of Peachtree Charter Middle School to have several keys copied and/or made in order for us to have a smooth school year. Please reference the list the below for specific keys and locations. We would also need an additional four(4) of our Master Key (M147A). We appreciate your attention to this. Room Number Key Serial # (if known) 600 614 700 718 147AA1 741 803 147AA52 MU-15 C	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	LOCKSMITH	7/26/2019 4:44:33 PM
100086	Lights Out in parking lot .We may need to reset sensors	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	GROUND	7/31/2019 7:13:00 AM
100587	Fire Alarm - Please check he fire alarm in the 3 modular trailers. Principal say it is not dialing out	PEACHTREE CHARTER MS - 1- CLASSROOM TRAILER	Peachtree Charter MS - 1 (Winward)	Region 1	FIRE SAFETY	8/2/2019 1:57:00 PM
101197	on the 7th grade hall boys restroom. There is the second stall were the toilet is stopped up will not flush.	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	PLUMBING	8/6/2019 7:27:00 PM
101198	trailer T13 window needs to be fixed.	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	GROUND	8/6/2019 7:31:00 PM
101199	on 6thgrade hall across from rm.614 in boys restroom the first urinal stall is stopped up.	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	PLUMBING	8/6/2019 8:25:00 PM
101200	on the 6th grade hall across from Rm. 634 in the girls restroom. The commode needs to be bolted down.	PEACHTREE CHARTER MS - 1	Middle Schools	Region 1	PLUMBING	8/6/2019 8:29:00 PM


Region 1 - 21 Total:

(Site Not Specified) - 21 Total:



Department

MS - Peachtree Charter Middle Facility



Report Criteria

- Shop is CARPENTRY, ELECTRICAL, HVAC, PAINTING / PRESSURE WASHING or PLUMBING
- Department is MS - Peachtree Charter Middle Facility
- Requested is greater than 06/01/2019

Work Order #	Reason	Asset ID	Parent Location	Target Date	Target Hours
(Site Not Specified)					
(Site Not Specified) > MS - Peachtree Charter Middle Facility					
88189	Roof Top Unit Annual PM	RTU-138054	Roof	4/29/2019	1
95199	RTU 11 not working	PEACHTREE CHARTER MS - 1	Middle Schools	6/9/2019	1
95318	need white traffic paint	PEACHTREE CHARTER MS - 1	Middle Schools	6/10/2019	1
96234	Room Too Hot Roof Top Unit RTU 20 is not Working The fan does not Come on it Needs Repairing. AC	PEACHTREE CHARTER MS - 1	Middle Schools	6/24/2019	1
96658	Room Too Hot DR Davis The air is Not Working in his office Room 107 RTU Unit 4 is not Coming on Needs Repairing	PEACHTREE CHARTER MS - 1	Middle Schools	7/12/2019	1
98320	Pipe leaking by room 803	PEACHTREE CHARTER MS - 1	Middle Schools	7/14/2019	1
98378	Paint - purchase 5 gals of Antique White Exterior for portable quad.	PEACHTREE CHARTER MS - 1- GROUND	Peachtree Charter MS - 1 (Winward)	7/14/2019	1
98557	Classroom - T1 - Purchase primer and semi-gloss finish DTM paint (Antique White) to paint metal stall partitions and doors in restroom. 5 gallons of each. See Chris Jackman if you have questions	PEACHTREE CHARTER MS - 1- CLASSROOM TRAILER-T1	Classroom Trailer	7/17/2019	1
98659	Repair blower motor in RTU #15.	PEACHTREE CHARTER MS - 1	Middle Schools	7/20/2019	1
98784	Have a leaking pipe in the ceiling. Location in near room 803 8th grade hallway. "Urgent"	PEACHTREE CHARTER MS - 1	Middle Schools	7/21/2019	1
98739	need a plumber have a leaking pipe near room 803. 8th grade hallway.	PEACHTREE CHARTER MS - 1	Middle Schools	7/22/2019	1
99096	Repair sewer cleanout between trailers.	PEACHTREE CHARTER MS - 1	Middle Schools	7/23/2019	1
99285	our elevator is n't moving from the lower level 6th grade floor.	PEACHTREE CHARTER MS - 1	Middle Schools	7/27/2019	1
99287	right in front of room 641 there's a leaking pipe. need a plumber	PEACHTREE CHARTER MS - 1	Middle Schools	7/27/2019	1
99355	RTU's units fans are not blowing, 3,4,11,12,13,14,18,20,&22.	PEACHTREE CHARTER MS - 1	Middle Schools	7/28/2019	1
99583	room 817 AC not working for the past three month's.	PEACHTREE CHARTER MS - 1	Middle Schools	7/30/2019	1
98555	Classroom - T2 - Repair or replace the dripping faucet in the girls restroom in Quad 5 - 8. Check all fixtures in all three quad trailers for proper operation.	PEACHTREE CHARTER MS - 1- CLASSROOM TRAILER-T2	Classroom Trailer	7/31/2019	1
99974	Paint - Please provide 5 gallons of Exterior A100 gloss Antique White Please deliver to Chris Jackman's office	PEACHTREE CHARTER MS - 1- CLASSROOM TRAILER-T5	Classroom Trailer	8/4/2019	1
100090	Room Too Hot 817 , 840, 724, 7th grade pod and 824	PEACHTREE CHARTER MS - 1	Middle Schools	8/5/2019	1
96803	Miscellaneous the Lights are not Working on the timer they are staying on in the School all day and night i need a electrician to Come out to Repair them	PEACHTREE CHARTER MS - 1	Middle Schools	8/31/2019	1

MS - Peachtree Charter Middle Facility - 20 Total:	20
(Site Not Specified) - 20 Total:	20
Grand Total (20 Records):	20